



## EXPLODED VIEW, PARTS AND PRICE LIST Phase I Model 22 Cal. 38T and C



This parts and price list is intended to be an informational guide in ordering Crosman parts. It is not instructional material and we therefore assume no responsibility for those who use same without proper factory training.



Hammer 38-059 is no longer available & can be replaced with the following parts

- 38B034 Trigger
- 38A102 Safety Link
- 38-106 Hammer Assy.

\*Factory Assembly Only

FOR REFERENCE ONLY:  
PARTS ARE NO LONGER  
AVAILABLE AND REPAIRS ONLY  
THROUGH SERVICE STATIONS  
SEE ENCLOSED REFERRAL LETTER